



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

0003

Inspection Report

Minerals Regulatory Program

Report Date: September 29, 2006

Supervisor DJH

Mine Name: East Side #1
Operator Name: Alpine Gem & Minerals
Paul Lamoreaux
195 North 200 East
P.O. Box 610
Parowan, Utah 84761

Permit number: S/053/078

Date: September 14, 2006

Time: 10:45 AM

Inspector(s): Doug Jensen

Other Participants: None

Mine Status: Inactive

Weather: Cloudy, light rain

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Inspected the site to check for any additional disturbances in the area. This permit has not been finalized; it is still awaiting finalization of a bond amount and the transfer of bond money from another site in the area. The Forest Service, who holds the bond, is handling the bond transfer.

Directions to Site:

See previous inspection report.

Inspection Summary:

The site remains unchanged since my last site visit.

Conclusions and Recommendations:

Will continue to monitor the site when I am in the area.

Inspector's Signature

Doug Jensen

Date:

9/29/06

dj:pb

cc:

Alpine Gem & Minerals

Steve Winslow, USFS, Beaver Ranger District

O:\M053-Washington\S0530078-EastSide1\Inspections\09142006insp.doc